SAFETY COMPLIANCE TESTING FOR FMVSS NO. 401 INTERIOR TRUNK RELEASE

2018 MAZDA 3 FOUR-DOOR PASSENGER CAR NHTSA VEHICLE NO. C20195401

U.S. DOT HEADQUARTERS 1200 NEW JERSEY AVENUE SE WASHINGTON, DC 20590



November 29, 2018

FINAL REPORT PREPARED FOR

U. S. DEPARTMENT OF TRANSPORTATION
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
ENFORCEMENT
NEF-220
OFFICE OF VEHICLE SAFETY COMPLIANCE
1200 NEW JERSEY AVENUE, SE
WASHINGTON, D.C. 20590

This publication is distributed by the U. S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the author(s) and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof. If trade or manufacturers' names or products are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Prepared By: _	Kerrin Bressant
Approved By: _	Kerrin Bressant
Accepted By: _	Kerrin Bressant
Acceptance Dat	5/9/19

					Technical Report Documentation Page
1. Report No.	2. Government	Accessi	on No.	3. Re	ecipient's Catalog No.
401-HQDLR-19-006					
4. Title and Subtitle			5. Re	eport Date	
E: 18				•	
Final Report of FMVSS N 2018 Mazda 3 Four-Do				6. Pe	erforming Organization Code
C20195401	oor rasseriger v	Sai, INIT	I SA NO.	HQD	N D
7. Author(s)	=				erforming Organization Report Number
					original dispersion in the point manifest
Joshua Campbell, Safety					N D DOT 40 404 000
Kerrin Bressant, Safety C 9. Performing Organization				_	DLR-DOT-19-401-006
9. Feriorining Organization	on Name and Ad	uress		10. V	Vork Unit No. (TRAIS)
U. S. DOT Headquarters	/NHTSA OVSC			11. 0	Contract or Grant No.
1200 New Jersey Avenue	е				on and or or and reco
Washington, DC 20590	I = == = = = A = I = = =			40.7	(B 1 1 1 1 1 1 1 1 1
12. Sponsoring Agency N	Name and Addre	SS		13. 1	ype of Report and Period Covered
United States Departmer	nt of Transportati	on		Final Test Report	
National Highway Traffic				November 29, 2018	
Office of Vehicle Safety (3 200		14. 8	Sponsoring Agency Code
1200 New Jersey Avenue, SE			NEE	220	
Washington, DC 20590 15. Supplementary Notes		NEF-	-220		
13. Supplementary Notes					
16. Abstract					
Compliance tests were c	onducted on the	subject 2	2018 Mazd	la 3 fo	ur-door passenger car in accordance
with the specifications of the Office of Vehicle Safety Compliance Test Procedure No. TP-401-01. Tes failures identified were as follows: NONE.			lest Procedure No. 1P-401-01. Test		
			bution	Statement	
OE			N. C.		T # 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Compliance Testing Natio			lational Highway Traffic Safety Administration	
		Technical Information Services Division NPO-411, Room E12-100			
500 COM 6000 BC 30			ew Jersey Avenue, S.E.		
		gton, DC 20590			
Email: ti		s@dot.gov			
10.0 '' 0' ''				02-493	3-2833
19. Security Classification report)	n (of this	21. No.	of Pages		22. Price
(report)					
UNCLASSIFIED		24	8	a)	
20. Security Classification	n (of this page)				
UNCLASSIFIED					9

Form DOT F 1700.7 (8-72)

TABLE OF CONTENTS

SECI	ION		PAGE
1	Introduc	ction	1
2	Test Pr	ocedure and Discussion of Results	2
3	Test Da	ata	3
	Test Da	ata Summary	4
		eparation Information	
		Trunk Release Operation	
4	Test Eq	quipment List and Calibration Information	8
5	Photogi	raphs	9
	Figure		
	5.1	Front of Vehicle	
	5.2	Left Side View of Vehicle	
	5.3	Right Side View of Vehicle	
	5.4	Left Rear Quarter View	
	5.5	Right Rear Quarter View	
	5.6	Vehicle Certification Label	
	5.7	Vehicle Trunk Compartment Interior Showing Original Equipment Installed	
	5.8	Vehicle Trunk Compartment Manual Release Mechanism	
	5.9	Release Mechanism with Test Equipment Attached	
	5.10	Test Observer in Trunk Compartment	
	5.11	Trunk Lid Exterior	

SECTION 1

INTRODUCTION

1.1 PURPOSE OF COMPLIANCE TEST

A 2018 Mazda 3 4-Door Passenger Car was tested to determine if the vehicle was in compliance with the requirements of FMVSS NO. 401. All tests were conducted in accordance with NHTSA/Office of Vehicle Safety Compliance (OVSC) Laboratory Test Procedure TP-401-01 dated August 8, 2007.

1.2 <u>TEST VEHICLE</u>

The test vehicle was a 2018 Mazda 3 4-Door Passenger Car. Nomenclatures applicable to the test vehicle are:

A. <u>Vehicle Identification Number</u>: 3MZBN1W3XJM255817

B. NHTSA Number: C20195401

C. Manufacturer: Mazda

D. Manufacture Date: 09/18

1.3 TEST DATE

The test vehicle was tested November 29, 2018.

SECTION 2

TEST PROCEDURE AND DISCUSSION OF RESULTS

2.1 TEST PROCEDURE

Prior to test, the test vehicle was inspected for completeness and systems operability, including battery capability and trunk closure function. The vehicle was then photographically documented as required by the NHTSA/OVSC Test Procedure. The owner's manual was reviewed, and pertinent trunk release information was noted.

The rear trunk manual release system vehicle tests were conducted with an occupant enclosed in the trunk compartment with the lid shut. An assistant was present and prepared to release the occupant if necessary. The compartment was evaluated with all removable equipment furnished by the manufacturer stowed in accordance with vehicle label instructions.

The procedure used consists of the following steps:

- Determine the means by which a trapped person within the trunk would escape from the compartment, e.g. pull of a T-handled release mechanism, rotation of fixed lever release mechanism, push of a button, etc.
- 2. For informational purposes, install a linear force transducer to the release mechanism determined above in order to record the force required to be applied by the trapped occupant to escape.
- 3. Verify that the release mechanism is visible in the darkened trunk (S4.2(a)), and determine method used, e.g. phosphorescence or auxiliary lighting. Some time may be required to allow for the eyes to adjust to the darkened environment within the trunk compartment. Photograph if possible the lighted release mechanism.
- 4. With the vehicle stationary and no key in the ignition (representing unoccupied vehicle), actuate the release mechanism and verify that the trunk lid releases from all latching positions. Record force required during 3 attempts to release trunk latching mechanism.
- 5. Repeat step 4 above, except with the engine idling (time with trunk lid latched not to exceed 30 seconds).

2.2 DISCUSSION OF RESULTS

The force required to release the trunk lid did not exceed 6 Newtons on any attempt. The data indicate compliance of the test vehicle's manual trunk release system for the No Key in Ignition and the Idling Vehicle trunk release tests.

SECTION 3 TEST DATA

DATA SHEET 1 FMVSS NO. 401 – TEST DATA SUMMARY

MODEL YEAR/MAKE/MODEL/BODY	2018 Mazda 3 Passenger Car	
VEHICLE NHTSA NUMBER: _C2019	VIN:3MZBN1W3XJM255817	
GVWR: 2,040 kg, 4,497 lbs.	ATE OF MANU	JFACTURE: 09/18
TEST LAB: Alexandria Maz		
		· · · · · · · · · · · · · · · · · · ·
		· · · · · · · · · · · · · · · · · · ·
	PASS/FAIL	COMMENTS
Automatic or Manual release		
mechanism inside the trunk		
compartment. S4.1	Dana	
If manual release, lighting feature	Pass	
is included.		A
S4.2(a)	Pass	Phosphorescence
Except as provided by S4.3(b),		
actuation of release mechanism		*
required by S4.1 completely	1	
releases trunk lid from all latching positions of the trunk lid latch.		
S4.3(a)	Pass	
DEMARKO		
REMARKS:		
RECORDED BY: Joshua Campbell	and Kerrin Bre	ssant DATE: November 29, 2018

APPROVED BY: Kerrin Bressant

DATA SHEET 2 TEST PREPARATION INFORMATION

MODEL YEAR/MAKE/MODEL/BODY STYLE:	2018 Mazda 3 4 Door Passenger Car			
VEHICLE NHTSA NUMBER: C20195401	TEST DATE: _	November 29, 2018		
TRUNK LOCATION: Rear_				
NUMBER OF TRUNK LATCHING POSITIONS:	One			
INTERIOR TRUNK RELEASE: Manual				
EQUIPPED WITH POWER CLOSURE ASSISTIN	NG DEVICE: No			
OWNER'S MANUAL DESCRIPTION OF TRUNK	RELEASE: Yes			
REMOVABLE EQUIPMENT DELIVERED IN TRU	JNK:			
SPARE TIRE: Yes Size: T12	<u>5/70D16</u>			
TIRE JACK: Yes				
LUG WRENCH: Yes				
OTHER:				
REMARKS: None				
RECORDED BY: Joshua Campbell and Kerrin B	ressant DATE: Nov	ember 29, 2018		
APPROVED BY: Kerrin Bressant				

MANUAL TRUNK RELEASE OPERATION

MODEL YEAR/MAKE/MODEL/BODY STYLE: 2018 Mazda 3 4-door passenger car					
VEHICLE NHTSA NUMBER: C20195401 TEST DATE: November 29, 2018					
Rotating Nothed used to actuate interior trunk release:					
Method used to actuate interior trunk release:Lever					
Can test personnel enter trunk and be closed within? _Yes_					
Size of occupant: 6' 0", medium frame					
Is there access to the trunk compartment by folding down rear seat or partition?Yes					
Does release mechanism require electric power? No					
Can release mechanism be easily seen inside the closed trunk? Yes					
Method used by vehicle manufacturer to ensure that release mechanism					
is visible in the closed trunk compartment: Phosphorescence					
Laboratory test method used to determine visibility of release mechanism: Release mechanism					
was activated with force gauge from inside of trunk.					

DATA SHEET 3 (Sheet 2 of 2) MANUAL TRUNK RELEASE OPERATION

	Force in Newtons Required to Release			
Vehicle Stationary	Trunk Lid	Trunk Released from		
(0 km/h)	(no requirement)	All Latching Positions	Pass/Fail	
NO KEY IN IGNITION				
Attempt 1	4	Yes	Pass	
Attempt 2	6	Yes	Pass	
Attempt 3	6	Yes	Pass	
Average	5.33	Yes	Pass	
ENGINE IDLING				
Attempt 1	5	Yes	Pass	
Attempt 2	6	Yes	Pass	
Attempt 3	4	Yes	Pass	
Average	5	Yes	Pass	

TEST RESULTS	PASS
REMARKS:	


RECORDED BY: Joshua Campbell and Kerrin Bressant DATE: November 29, 2018

APPROVED BY: Kerrin Bressant


SECTION 4 TEST EQUIPMENT LIST AND CALIBRATION INFORMATION

EQUIPMENT	DESCRIPTION	MODEL/ SERIAL NO	CAL. DATE	NEXT CAL. DATE
SHIMPO	DIGITAL MULTI METER 756202	FGV-200HX	04/13/2006	04/12/2008

SECTION 5 PHOTOGRAPHS




2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401




2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401

FIGURE 5.2 LEFT SIDE VIEW OF VEHICLE




2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401

FIGURE 5.3 RIGHT SIDE VIEW OF VEHICLE




2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401

FIGURE 5.4 LEFT REAR QUARTER VIEW



2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401

FIGURE 5.5 RIGHT REAR QUARTER VIEW




2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401

VEHICLE CERTIFICATION LABEL



2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401

FIGURE 5.7
VEHICLE TRUNK COMPARTMENT INTERIOR
SHOWING ORIGINAL EQUIPMENT INSTALLED



2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401


FIGURE 5.8 VEHICLE TRUNK COMPARTMENT MANUAL RELEASE MECHANISM



2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401



2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401



2018 MAZDA 3 NHTSA NO. C20195401 FMVSS NO. 401